



5 Davis Farm Road, Portland, ME 04103 | consolidated.com | NASDAQ: CNSL

March 5, 2020

Federal Communications Commission  
445 12th Street SW  
Washington, DC 20554  
Att: Carmell Weathers  
Wireline Competition Bureau

Subject: Network Notification No. 139

Public Notice of Copper Retirement Under Rule 51.333

This Notice, pursuant to CFR 47, Subsection 51.333, advises of the following Network change(s) and/or improvement(s) within Consolidated Communications of Vermont Company, LLC d/b/a Consolidated Communications (“Consolidated”) and the scheduled implementation date.

**Vermont Wire Centers:**

<b>Consolidated Central Office CLI:</b>	<b>Central Office Name:</b>	<b>Consolidated RT CLI :</b>	<b>Municipality:</b>	<b>Route and Pole:</b>	<b>Street Address:</b>
EFFDVTMA	East Fairfield	EFFDVT02	East Fairfield	Route 2 P3	1749 Whitney RD
JCVLVTSC	Jacksonville	WHHMVT02	Whitingham	Route 99 P1	26 Dam RD
LYVLVTCE	Lyndonville	WHLCVTAE	Wheelock	Route 19-5 P18	4944 So Wheelock RD
STALVTBA	St. Albans	FRFDVT06	Fairfield	Route 32-4 P3	2053 Reynolds RD
STBYVTSM	St. Johnsbury	STBYVT01	St. Johnsbury	Route 9 P31	21 Mud Hollow RD
STBYVTSM	St. Johnsbury	STBYVT32	St. Johnsbury	TS120 P2528	2394 Duck Pond RD
SRTNVTAR	Stratton	WNHLVT06	Winhall	Route 49 P1	14 French Hollow RD
BARTVTCH	Barnet	BARNVT05	Barnet	Route 1 P92	2805 West Barnet RD

**Planned Implementation or Retirement Date:** 08/01/2020

**Description of Change:**

Consolidated Communications Inc. will be installing a Digital Line Subscriber Access Multiplexer (DSLAM) to provide Digital Subscriber Line (DSL) service. No change to existing circuits.



In addition, Consolidated Communications Inc. will be replacing the copper (metallic) feeder facilities with fiber optic cable and Digital Loop Carrier (DLC) systems. The public notice of this network change will identify the services that will be transferred to the DLC. Changes may occur to existing

**Description of Change (cont'd):**

circuits because they are not compatible with DLC. Any existing UNE xDSL or Digital Design Loop (DDL) services may be disconnected with this network change.

**Description of Foreseeable Impact:**

After the planned network changes are implemented, there will be no copper (metallic) loop facilities between Consolidated Communication’s Central Offices listed and the remote terminal in the affected area. Copper (metallic) sub-loop facilities will remain in place between Consolidated Communication’s Remote Terminal and customer premises in the affected area.

**CLEC SERVICES IMPACTED**

<b>CLEC NAME/CCNA/ACNA</b>	<b>Consolidated RT CLLI</b>	<b>CIRCUIT TYPE/SERVICE (e.g. DSL)</b>	<b>CIRCUIT ID</b>
NONE			

Attachment: Certificate of Service

Contact: Rick Cimon  
603-645-1970  
richard.cimon@consolidated.com

Barbara Galardo (Regulatory)  
207-535-4126  
barbara.galardo@consolidated.com