Before the Federal Communications Commission Washington, D.C. 20554

| In the Matter of |) | |
|-------------------------------------|---|------------------------|
| Wilks License Company – Lubbock LLC |) | File No. EB-10-DL-0020 |
| Licensee of Radio Station KLLL |) | |
| Facility ID # 36954 |) | NOV No. V201032500002 |
| Lubbock, Texas |) | |
| |) | |
| |) | |

NOTICE OF VIOLATION

Released: 4/14/2010

By the District Director, Dallas Office, South Central Region, Enforcement Bureau:

- 1. This is a Notice of Violation ("Notice") issued pursuant to Section 1.89 of the Commission's Rules¹ to Wilks License Company Lubbock LLC (Wilks), licensee of radio station KLLL in Lubbock, Texas.
- 2. On February 25, 2010, an agent of the Commission's Dallas Office inspected/monitored radio station KLLL, located at Lubbock, Texas, and observed the following violation(s):
 - a. 47 C.F.R. § 73.317(d): "Any emission appearing on a frequency removed from the carrier by more than 600 kHz must be attenuated at least 43 + 10 Log10 (Power, in watts) dB below the level of the unmodulated carrier, or 80 dB, whichever is the lesser attenuation." At the time of inspection, the spectrum sample from radio station KLLL had spurious emissions on 95.0, 97.6, 97.8, and 99.8 MHz which were not attenuated as required.
- 3. On February 25, 2010, during the inspection, radio station KLLL had a spurious intermodulation product emission on 109.15 MHz. The inter-modulation product included audio from 95.5 MHz, 102.5 MHz and others. The modulation from the 109.15 MHz inter-modulation produced varying signal levels on the Lubbock Preston Smith International Airport Instrument Landing System (ILS) channel 109.5 MHz. The signals on the ILS channel were observed at one mile from the transmitter site as high as 30 dB above the channel noise floor and below the minimum attenuation level required by section 73.317(d) of the Commission's Rules. Although below the emission mask in section 73.317(d) of the Commission's Rules, these signals appear to be the cause of one of the reports which placed the ILS out of service, specifically a report of disruption in

¹ 47 C.F.R. § 1.89.

the ILS at ten miles south of the airport runway, and required corrective action by the station.² Radio station KLLL's transmitter site is approximately 1.5 miles west of the center line point, which is nine miles south of the Lubbock Preston Smith International Airport runway. Station KLLL's engineer adjusted the transmitter removing the spurious emission on 109.15 MHz.

4. Pursuant to Section 308(b) of the Communications Act of 1934, as amended,³ and Section 1.89 of the Commission's Rules, Wilks License Company – Lubbock LLC, must submit a written statement concerning this matter within twenty (20) days of release of this Notice. The response must fully explain each violation, must contain a statement of the specific action(s) taken to correct each violation and preclude recurrence, and should include a time line for completion of pending corrective action(s). The response must also fully explain the steps it is taking to ensure that spurious emissions do not interfere with Instrument Landing Equipment, utilizing frequencies between 108.0 MHz and 118.0 MHz, onboard aircraft passing within two miles of its transmitter site. The response must be complete in itself and signed by a principal or officer of the licensee. All replies and documentation sent in response to this Notice should be marked with the File No. and NOV No. specified above, and mailed to the following address:

Federal Communications Commission Dallas Office 9330 LBJ Freeway, Suite 1170 Dallas, Texas 75243

- 5. This Notice shall be sent to Wilks License Company Lubbock LLC at its address of record.
- 6. The Privacy Act of 1974⁴ requires that we advise you that the Commission will use all relevant material information before it, including any information disclosed in your reply, to determine what, if any, enforcement action is required to ensure compliance. Any false statement made knowingly and willfully in reply to this Notice is punishable by fine or imprisonment under Title 18 of the U.S. Code.⁵

FEDERAL COMMUNICATIONS COMMISSION

James D. Wells District Director Dallas District Office South Central Region Enforcement Bureau

_

² See 47 U.S.C. § 73.1350(e) (requiring a broadcast station, operating in a manner likely to significantly disrupt operation of other stations or pose a threat to life or property, to terminate operation within three minutes unless antenna input power is reduced sufficiently to eliminate any excess radiation).

³ 47 U.S.C. § 308(b).

⁴ P.L. 93-579, 5 U.S.C. § 552a(e)(3).

⁵ 18 U.S.C. § 1001 et seq.