



1 Davis Farm Road
Portland, Maine 04103

May 6, 2015

Federal Communications Commission
Attn: Carmen Weathers
445 12th Street, SW
Washington, DC 20554

Subject: Network Notification No. 93

Short Term Public Notice Under Rule 51.333a
(Less than 6 months notice)

This Notice, pursuant to CFR 47, Subsections 51.325 – 51.335 advises of the following Network change(s) and/or improvement(s) within Northern New England Telephone Operations LLC ("NNETO"), d/b/a FairPoint Communications – NNE and the scheduled implementation date.

New Hampshire Wire Centers:

Fitzwilliam, New Hampshire
FTZWNHUT

Fitzwilliam Remote Terminal
FTZWNH01

Greenfield, New Hampshire
GNFDNHMA

Greenfield Remote Terminal
GNFDNHAK

Greenfield, New Hampshire
GNFDNHMA

Greenfield Remote Terminal
GNFDNHAL

Rindge, New Hampshire
RNDGNHCE

Rindge Remote Terminal
RNDGNHCI

Springfield, New Hampshire
SPFRNHMS

Chesterfield Remote Terminal
CHFDNHBA

Springfield, New Hampshire
SPFRNHMS

Chesterfield Remote Terminal
CHFDNHBC

Springfield, New Hampshire
SPFRNHMS

Chesterfield Remote Terminal
CHFDNHBB

Walpole, New Hampshire
WLPLNHWP

Walpole Remote Terminal
WLPLNHBP

Walpole, New Hampshire
WLPLNHWP

Walpole Remote Terminal
WLPLNHBP

West Stewartstown, New Hampshire
WSTWNHBS

Stewartstown Remote Terminal
SWTWNHAE

West Stewartstown, New Hampshire
WSTWNHBS

Pittsburg Remote Terminal
PSBGNHAI

West Stewartstown, New Hampshire
WSTWNHBS

Pittsburg Remote Terminal
PSBGNHAI



Planned Implementation or Retirement Date:

December 1, 2015

Description of Foreseeable Impact These network changes will create the potential for spectral interference on the CO-based ADSL and/or a Digital Design Loop (DDL) loops that share the same binder groups as the RT ADSL within the copper distribution feeder cable past the Feeder Distribution Interface (FDI).

Description of Change: When FP is installing a Digital Line Subscriber Access Multiplexer (DSLAM) or Litespan to provide Digital Subscriber Line (DSL) service from a Remote Terminal (RT) that is less than 30,000 feet from the Central Office and only when copper feeder is present between the Central Office and RT.

Attachment: Certificate of Service

Contact: Corey Peterson
603-528-7315
corey.peterson@fairpoint.com

Barbara Galardo (Regulatory)
207-535-4126
bgalardo@fairpoint.com

